












#	ART. NR	QUANTITY
1	820	1
2	830	1
3	821	1
4	831	1
5	120	2
6	130	2
7	350	3
8	730	3






							
D1	C	E	A	O11	F1	P6	M6
34	34	34	40	1	14	24	12









1

$\varnothing 15/12$	$\varnothing 8 \times 30$	
		
C	A	F1
12	12	6



2



	$\varnothing 15/12$	
D1	C	M6
12	8	6
$\varnothing 8 \times 30$	$\varnothing 6,3 \times 13 \text{ mm}$	
A	P6	F1
8	12	4



2x



3

	
D1	F1
8	4





4



	
C	M6
8	6
$\varnothing 8 \times 30$	$\varnothing 6,3 \times 13 \text{ mm}$
	
A	P6
8	12





5







6





7



8



9



10

