





MARKUS 1

1





#	ART. NR	QUANTITY
1	401	1
2	402	1
3	403	1
4	101	1
5	102	1
6	001	2
7	601	2
8	801	1




							
B	O	A	F10	R2	S1	E1	
12	1	22	50	4	2	12	
							
H4	G7	O12	P1	Z1	F1	O10	P2
6	6	1	12	1	4	2	4





1



2




	
H4	F1
6	4
	
O10	P2
2	4





3

		
B	O	E1
8		8






4

		
B	O	E1
4		4





5

	
F10	Z1
50	1




6


012
1





7


$\varnothing 4.0 \times 16 \text{mm}$	$\varnothing 35 / \text{KR}-15$
	
12	6
$4.0 \times 42 \text{mm}$	
	
4	2



8






9






MARKUS 2

2



#	ART. NR	QUANTITY
1	410	1
2	411	2
3	110	1
4	111	1
5	112	1
6	810	1
7	310	1
8	510	1
9	610	1
10	710	1
11	301	2
12	305	1
13	050	1
14	010	1




									
8	1	37	30	4	2	8	8	8	8
									
2	2	8	2KPL	12	1	6	1		






1

	 $\varnothing 15/12\text{mm}$	 $\varnothing 8 \times 30\text{mm}$
D1	C	A
6	2	20




2






	 $\varnothing 8 \times 30\text{mm}$
D1	A
2	9
 $\varnothing 15/12\text{mm}$	 $3.5 \times 13\text{mm}$
C	P2
6	8
 L=350	
PR	F1
2KPL	6
	
J4	H4
1	2






3








4




5







6











12




13



14





15






MARKUS 3

3



#	ART. NR	QUANTITY
1	420	1
2	421	1
3	422	1
4	120	1
5	121	1
6	220	2
7	820	1
8	620	1
9	621	1
10	020	3









						
B	O	A	F10	R2	S1	E1
22	1	26	30	4	2	22
						
H4	G7	P1	Z1	P2	F8	
4	4	8	2	6	4	



1

$\varnothing 8 \times 30 \text{ mm}$  A	 H4
22	4




2

		
B	O	E1
4		4





3

		
B	O	E1
10		10




4

		
B	O	E1
8		8





5

3.5x13mm 		
P2	F10	F8
6	20	4
		
Z1		
2		





6



ø4.0x16mm 	ø35/KR-15 
P1	G7
8	4
4.0x42mm 	
R2	S1
4	2




7



8



9








MARKUS 4

4





#	ART. NR	QUANTITY
1	430	1
2	431	2
3	530	3
4	130	1
5	131	1
6	030	1
7	630	1
8	631	1
9	830	1







						
B	O	A	F10	R2	S1	E1
12	1	16	30	4	2	12
						
H=0	ø35/KR-15	ø4.0x16mm				
H4	G7	P1	J4	F1		
5	5	10	14	4		





1





2






3




4



5





6





7


4.0x16mm P1 10	35/KR-15 G7 5
4.0x42mm R2 4	S1 2



8



9










MARKUS 5

5



#	ART. NR	QUANTITY
1	440	1
2	441	1
3	442	1
4	443	1
5	444	1
6	140	1
7	141	1
8	240	1
9	540	2
10	040	2
11	640	1
12	840	1
13	740	1
14	741	1
15	301	4
16	306	2
17	051	2




22	1	44	50	6	3	22	2	2	2
2	2	12	1	2KPL	8	5	9	4	2






1

	
A	D1
20	2





2

	
J4	A
4	4
	
H4	F1
2	4
	
L-350	3.5x13mm
	
PR	P2
2KPL	4






3

		
J4	A	C
5	4	2
		
L-350	3.5x13mm	
PR	P2	
2KPL	4	





4

			
B	O	E1	E
4		2	2





5

		
B	O	E1
14		14






6

		
B	O	E1
4		4








7

		
F10	F8	Z1
30	5	1




8






13

$\varnothing 4.0 \times 16 \text{mm}$	$\varnothing 35 / \text{KR}-15$
	
4	2
$4.0 \times 42 \text{mm}$	
	
2	1



14



15

