


















R-7












No.	T(mm)	L(mm)	W(mm)	pcs.
1	18	648	170	1
2	16	716	397	1
4	16	716	397	1
3	16	716	397	1
5	16	778	354	1
6	16	490	354	1
7	16	720	420	1
8	16	720	400	1
9	16	1284	200	1
10	16	1284	100	1
11	16	648	379	1
12	16	1284	400	1
13	16	1284	383	1
14	3	1292	327	1
15	3	1292	327	1





1



2



3



4

M1

M1

x2

12

5

M1

P

Z1a

8

Z1a

M1

M1

P x2

M1 x5

Z1a x2


6

Diagram illustrating the assembly of the top plate (11) using various fasteners (Z4, K, M, P). The components are shown in a perspective view, with dashed lines indicating the placement of the fasteners. The fasteners are labeled as follows:


- Z4: Screws (4 per corner)
- K: Screws (4 per edge)
- M: Screws (4 per corner)
- P: Screws (4 per edge)

The diagram shows the top plate (11) being attached to the frame. The fasteners are used to secure the plate to the frame. The diagram also includes a detail view of the fasteners (Z4, K, M, P) and a sequence of steps showing the assembly of the fasteners.


7




8




9




10




11










12




13




14



15



16



17

