





XL RUMBA

BJ01 ☐

DL01 ☐


WH01 ☐

SO01 ☐





Ersatzteil Nummer	Dimension
RBA.201 x4	750x320,5x15
RBA.301 x4	423x283x15
RBA.401 x2	424x293x15
RBA.901 x2	718x100x15
RBA.902 x2	750x60x18
RBA.801 x8	278x283x5

Ersatzteil Nummer	Dimension
RBA.108	1850x320x15
RBA.109	1850x320x15
RBA.506	1850x298x15
RBA.601	436x1859x2,5
RBA.602	291x1859x2,5
RBA.701	450x1815x15
RBA.903	1821x60x16



Ersatzteil Nummer	Dimension
RBA.101	1850x320x15
RBA.102	1850x320x15
RBA.501	1850x298x15
RBA.601	436x1859x2,5
RBA.602	291x1859x2,5
RBA.701	450x1815x15
RBA.903	1821x60x16

Ersatzteil Nummer	Dimension
RBA.105 x2	265x384x15
RBA.204x2	1500x384,5x15
RBA.303	1398x160x15
RBA.305	494x357x15
RBA.503 x2	265x362x15
RBA.609 x2	490x274x2,5
RBA.706 x2	496x230x15
RBA.905	1400x160x15
RBA.906	1400x60x16
RBA.913	1500x60x18





RBA.801



RBA.301 =



RBA.401



T3

1

F10	P14	T9
5	5	7

P1	H	T4
20	3	1


R2	P7	D2	C	A	L2	S1	J3	G
2	10	18	18	12	12	1	8	3














O7	L9	E	J12	P5	L2	P1	H	T4
1	1	16	16	7	10	20	3	1

R2	P7	D2	C	A	L2	S1	J3	G
2	10	18	18	12	12	1	8	3




2

L=20mm	±15/12mm	±8x30mm				±4.0x16mm	±60/20mm	±4.0x25mm
								
D2	C	A	T9	T4	T3	P1	F10	P14
18	18	12	7	1	1	10	5	5












3




4









5



6



φ3.0x20mm		
		
P7	L2	L
9	9	12




7

4.0x16mm




P1

10



x1





B

RBA.903


x5

x1



8


H=0



H

3

35/0mm



G


3

3.5x13mm




P5

6




G




A

B





G





G

RBA.701





$\varnothing 5/16\text{mm}$  J3	 E	 J12	$\varnothing 4.0 \times 30\text{mm}$  R2	L=128mm  S1
8	16	16	2	1





RBA.801 = max. 2kg






RBA.301 = max. 5kg








RBA.401







								
								T3
								1
$\varnothing 60/20\text{mm}$	$\varnothing 4.0 \times 25\text{mm}$							
F10	P14							T9
5	5							7
$\varnothing 10 \times 50\text{mm}$		$\varnothing 3.5 \times 13\text{mm}$	$\varnothing 4.0 \times 16\text{mm}$	H=0		$\varnothing 4.0 \times 30\text{mm}$	$\varnothing 3.0 \times 20\text{mm}$	L=20mm
O7	L9	E	J12	P5	L2	P1	H	T4
1	1	16	16	7	10	20	3	1
$\varnothing 4.0 \times 30\text{mm}$	$\varnothing 3.0 \times 20\text{mm}$	L=20mm	$\varnothing 15/12\text{mm}$	$\varnothing 8 \times 30\text{mm}$		L=128mm	$\varnothing 5/16\text{mm}$	$\varnothing 35/0\text{mm}$
R2	P7	D2	C	A	12	S1	J3	G
2	10	18	18	12	12	1	8	3

3B :


L=20mm	±15/12mm	±8x30mm				±4.0x16mm	±60/20mm	±4.0x25mm
								
D2	C	A	T9	T4	T3	P1	F10	P14
18	18	12	7	1	1	10	5	5






391mm



339mm





13




14






15



16





±3.0x20mm		
P7	L2	L
9	9	12



17

4.0x16mm
P1
10




RBA.902




RBA.903

x5






x1





18






H=0	35/0mm	3.5x13mm
H	G	P5
3	3	6




RBA.701







$\varnothing 5/16\text{mm}$  J3 8	 E 16	 J12 16	$\varnothing 4.0 \times 30\text{mm}$ L=128mm  R2 2	 S1 1
--	---	---	---	--



21



$\pm 6,3 \times 9 \text{ mm}$	$\pm 7/2 \text{ mm}$	$\pm 4.0 \times 16 \text{ mm}$		
				
M4	K7	J5	P1	T9
4	2	2	4	4



22



$\pm 4.0 \times 16 \text{ mm}$







P1
4






23









$6,4 \times 50 \text{ mm}$	
	
B	O
5	1






5/45mm	Ø10x50mm
	
O3	O7
2	2


L=20mm  D2 16	15/12mm  C 16	8x30mm  A 16	60/20mm  F10 6	4.0x25mm  P14 6	 T9 5	4.0x16mm  P1 5
--	--	---	---	--	---	---




26




27







28






29





$\pm 3.0 \times 20 \text{mm}$	
	
P7	L
4	10





30





$L=128 \text{mm}$

S1
2

$\pm 35/0 \text{mm}$	
	
G	H
4	4
$\pm 3.5 \times 13 \text{mm}$	$\pm 4.0 \times 30 \text{mm}$
	
P5	R2
8	4



31





32

